



## Helmet Clearance Procedure

Clearance will be checked by the safety director and/or his/her designee.

- The driver must be strapped in, with all safety gear in place and race ready.
- There shall be no less than one-inch clearance between the top of the driver's helmet and the bottom of the top cage bars, three inches is recommended.